
CITY OF BALTIMORE WET SMOKE AND DYED	Page 1 of 3				
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/27/2008			
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04			
Manhole ID: S19M002MH	Test ID: 1029-577	Notifications Made:X_ Residents, Fire, 311			



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM						Page 2 of 3					
ļ	Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO					Date: 08/27/2008				
	Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_						Supervisor: E.R. Crew: 04			
	Manhole ID: S19M_002MH Test ID: 1029-577					Notifications Made:X Residents, Fire, 311					
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)											
Defect		Source			Sector	Drai	nage			Di i N	
No. 1	468 S BENTALOU ST.	Type 02	12	,	02		rea I6	03		Photo Number 1029-577_OB01-01.jpg	
- 1	400 3 BENTALOU 31.	02	12		02	-	10	03		1029-377_ОВОТ-01.jpg	
						ļ					
						-					
						-					
		OB	SERV	/ΔΤ	ION CO	DES					
	Source Type	l SE	Locat				_	Sector		Severity	
01 Ma	ain Sewer 10 MH Frame	01 Paved 0				ved		Public	01	No Smoke	
	ervice Line 11 Storm Drain	02 Asphalt			Field/W			Private		Trace	
	eanout 12 Catch Basin	03 Paved 0								Moderate	
	ownspout 13 Storm MH	04 Drivewa			Golf Co	urse				Major	
	ea Drain 14 Storm Ditch	05 Sidewal			Other						
	vy. Drain 15 Excavation	06 Curb									
	air. Drain 16 Water Line	07 Yard - F									
	ound. Drai 17 Tele. Pole	08 Yard - B									
09 Blo	dg. Interio 18 Other	09 Yard - S	Side								

PAGE 3 of 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 577 Date: 08/27/2008 Basin: LL - 44 Manhole ID: S19M__002MH Defect No: OB01 Supervisor: E.R. Crew: 04 Dye Test Recommended: N

Location: 468 S. BENTALOU ST.

Source Type: 02 Service Line Sector: 02 Private

Location: 12 Alley Severity: 03 Moderate Drainage Area: 16

Comments: SMOKE IS COMING FROM BOTTOM OF CONCRETE SLAB.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 1029-577_OB01-01.jpg